



S81-Y

Distance sensor with laser emission and time of flight measurement



INSTRUCTION MANUAL

CONTROLS

OUT LED (vellow)

The yellow LED Son indicates the activation of the Son indicates the activation of the output.

OUT LED (yellow)

The yellow LED TO ON indicates the activation of the

POWER ON/ALARM LED (green)

The green LED blinking indicates received signal absence or distance target outside the measurement range. The green LED on indicates the power of the sensor.

UNIT PUSH-BUTTON

The teach-in procedure of the digital threshold of the output is activated by pressing the push-button.

OUT PUSH-BUTTON

The teach-in procedure of the digital threshold of the T output is activated by pressing the push-button.



See the "THRESHOLD SETTING" paragraph for digital threshold teachin procedure


INSTALLATION

The sensor can be positioned using threaded M5 holes with max. 6 mm


Do not apply excessive torque when adjusting (max 2.2 Nm)

The operating distance is measured starting from the front surface of the sensor optics.

CONNECTIONS



DIMENSIONS



TECHNICAL DATA

	S81-Y-PPV	S81-Y-NNV
Power supply:	24 +/- 20% VDC limit values (Class 2 UL 508)	
Ripple:	2 Vpp max.	
Consumption	120 mA max (100 mA @ 24 V)	
(output current excluded):	O DND or NDN or to de	
Outputs:	2 PNP or NPN outputs 30 VDC max. (short-circuit protection)	2 PNP or NPN outputs 30 VDC max. (short-circuit protection)
	analogue output with 0-10 V (max. output current = 10 mA - 1 kΩ minimum resistence load)	analogue output with 0-10 V (max. output current = 10 mA - 1 kΩ minimum resistence load)
Switching mode	Light	Light
Output current:	100 mA max.	
Measurement range:	300 4000 mm (90% withe) 300 3000 mm(18% gray) 300 2000 mm (4% black)	
Linearity:	<1% (24 VDC, 25 °C, with 90% white target)	
Repeatability:	+/- 4mm	
Hysteresis:	20 mm	
Temperature drift:	< 1 mm/°C	
Response time:	5 ms	
Switching frequency:	80 Hz	
Indicators:	UT LED (yellow) / OUT LED (yellow) / POWER ON-ALLARM (green)	
Setting:	♦ OUT and ♣ OUT push-buttons	
Warm-up:	15 min.	
Operating temperature:	0 50 °C	
Storage temperature:	-20 70 °C	
Dielectric strength:	500 VAC 1 min., between electronics and housing	
Insulating resistance:	$20~\text{M}\Omega$ 500 VDC, between electronics and housing	
Typical spot dimension:	Ø 3.5 mm at 30 cm - Ø 7 mm at 4 m	
Emission type:	RED LASER (λ = 665nm): Class 2 EN 60825-1 (1994) +A1(2002) +A2(2001),	
Ambient light rejection:	According to EN 60947-5-2	
Vibrations:	0.5 mm amplitude, 10 55 Hz frequency, for every axis (EN60068-2-6)	
Shock resistance:	11 ms (30 G) 6 shock for every axis (EN60068-2-27)	
Housing material:	ABS	
Lens material:	PMMA	
Mechanical protection:	IP67	
Connections:	M12 5-pole connector	
Weight:	92 g. max.	

THRESHOLD SETTING

The sensor uses the patent-covered EASY TOUCH™ technology that allows a rapid and safe self-setting of the product.

EASY TOUCH™

Place the background or the object to be suppressed inside the operating range.

Press the UUT push-button until the UUT LED is OFF.

The sensor is now ready to detect all objects in the operating field distinguishing them from the suppressed background (\$\Bullet\$ LED OUT turns ON). Repeat, if necessary, the same procedure for **o** ouput.


Both digital outputs switch in light mode: when the target detected is inside the acquired threshold, the related output is high.

Viceversa the output is low when the target detected is outside the threshold. Switching thresholds are set by factory at value 3700 mm.

Both digital outputs switch in the light mode.

When the target is inside the detection threshold the corresponding output is at 24 V. Viceversa, if the measured target is outside the detection threshold, the corresponding output is at 24 V.

The switching thresholds are set by default at 3700 mm.



SAFETY WARNINGS

All the safety electrical and mechanical regulations and laws have to be respected during sensor functioning. The sensor has to be protected against mechanical damages. The sensor has to be protected against mechanical damages.



Place the given labels in a visible position close to the laser emission.

Do not look directly into the laser beam!

Do not point the laser beam towards people!

Eye irradiation for over 0.25 seconds is dangerous; refer to class 2 standard (EN60825-1). These sensors are not conform to safety applications!

The sensors are NOT safety devices, and so MUST NOT be used in the safety control of the machines where installed

DECLARATION OF CONFORMITY

We Datalogic Automation declare under our sole responsibility that these products are conform to the 2004/108/CE and successive amendments.

Datalogic Automation warrants its products to be free from defects.

Datalogic Automation will repair or replace, free of charge, any product found to be defective during the warranty period of 36 months from the manufacturing date.

This warranty does not cover damage or liability deriving from the improper application of Datalogic Automation products.

DATALOGIC AUTOMATION srl

Via Lavino 265 - 40050 Monte S.Pietro - Bologna – Italy

Tel: +39 051 6765611 - Fax: +39 051 6759324 www.datalogic.com

DATALOGIC AUTOMATION cares for the environment: 100% recycled paper.

DATALOGIC AUTOMATION reserves the right to make modifications and impro

© 2008 - 2014 Datalogic Automation - ALL RIGHTS RESERVED - Protected to the fullest extent under U.S. and Section 2014 Detailings Automation A.E. North 3.4. Section 2014 Detailing the international laws. Copyling, or altering of this document is prohibited without express written consent from Datalogic Automation. Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S.A. and the E.U.

826003304 Rev.D